

Certificate Reference: MJ000000014


| DETAILS OF THE CONTRACTOR | | DETAILS OF THE INSTALLATION | | DETAILS OF THE CLIENT/LANDLORD | |
|---------------------------|---|-----------------------------|---|--------------------------------|--|
| Trading Title: | Priority Home Service Limited | Installation Address: | Installation Address 134 Vincent Road Sheffield | Client Address: | West One Accomodation 281 Ecclesall Rd Sheffield |
| Address: | Unit 4, Neepsend Triangle 1 Burton Road Sheffield | | Post Code: S7 1BX | | Post Code: S11 8NX |
| Gas Safe No: | 539093 | Telephone No: | 0330 9991999 | Telephone No: | |

| APPLIANCE DETAILS | | | | | | | |
|-------------------|----------|----------------|------|-------------|-----------|----------------------|---------------------|
| | Location | Appliance Type | Make | Model | Flue Type | Landlord's Appliance | Appliance Inspected |
| 1 | Kitchen | CHB | Main | Combi 24 HE | RS | Yes | Yes |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |

| INSPECTION DETAILS | | | | | | | | AUDIBLE CO ALARM | | | |
|--------------------|-----------------------------|--|-------------------------------------|------------------------------------|---|-----------------------|--------------------|-----------------------|--------------------------|---------------------|----------------------------------|
| | Combustion Analyser Reading | Operating Pressure in mbar or heat input in kW | Safety Devices(s) Correct Operation | Ventilation Provision Satisfactory | Visual Condition of Flue and Termination Satisfactory | Flue Performance Test | Appliance Serviced | Appliance Safe To Use | Approved CO alarm fitted | Is CO alarm in date | Testing of CO alarm satisfactory |
| 1 | 6.0/11ppm/0.0001 | 10mbar BP/22.85KW | Yes | Yes | Yes | Pass | No | Yes | Yes | Yes | Yes |
| 2 | | | | | | | | | | | |
| 3 | | | | | | | | | | | |
| 4 | | | | | | | | | | | |

| DEFECT(S) IDENTIFIED | | REMEDIAL ACTION TAKEN | | NOTICE & LABEL ISSUED |
|----------------------|--|-----------------------|--|-----------------------|
| 1 | | | | |
| 2 | | | | |
| 3 | | | | |
| 4 | | | | |

| | | | | | |
|--|------|--|-----|-----------------------------------|------------|
| Outcome of gas installation pipework visual inspection | PASS | Is the Emergency Control Valve access satisfactory | YES | Outcome of gas tightness test | PASS |
| Outcome of gas supply pipework visual inspection | PASS | Is the Protective Equipotential bonding satisfactory | YES | NEXT INSPECTION DUE ON OR BEFORE: | 29/10/2016 |

| SIGNATURES | | | | | |
|---------------------------|-----------------|---------|---|-----------------|------------|
| Report Issued By: Name: | Matthew Jackson | Signed: |  | Date Inspected: | 29/10/2015 |
| Report Received By: Name: | | Signed: | | Date Received: | |
| | | | | Gas ID No: | 3700878 |