



LANDLORD/HOME OWNER GAS SAFETY RECORD

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998.

Certificate Reference: CW000064

DETAILS OF THE CONTRACTOR		DETAILS OF THE INSTALLATION		DETAILS OF THE CLIENT/LANDLORD	
Trading Title:	Priority Home Service Limited	Installation Address:	Rented 98 Alderson Road Sheffield Post Code: S2 4UD	Client Address:	West One Accomodation 281 Ecclesall Rd Sheffield Post Code: S11 8NX
Address:	Unit 4, Neepsend Triangle 1 Burton Road Sheffield Post Code: S3 8BW	Telephone No:	N/A	Telephone No:	n/a
Gas Safe No:	539093	Telephone No:	0330 9991999	Telephone No:	n/a

APPLIANCE DETAILS							
	Location	Appliance Type	Make	Model	Flue Type	Landlord's Appliance	Appliance Inspected
1	Bathroom	CHB	Baxi	80e	RS	Yes	Yes
2	Kitchen	HOB	Unknown	N/A	FL	Yes	Yes
3							
4							

INSPECTION DETAILS									AUDIBLE CO ALARM		
	Combustion Analyser Reading	Operating Pressure in mbar or heat input in kW	Safety Devices(s) Correct Operation	Ventilation Provision Satisfactory	Visual Condition of Flue and Termination Satisfactory	Flue Performance Test	Appliance Serviced	Appliance Safe To Use	Approved CO alarm fitted	Is CO alarm in date	Testing of CO alarm satisfactory
1	0.0003	11mbar	Yes	Yes	Yes	N/A	No	Yes	Yes	Yes	Yes
2	N/A	20	Yes	Yes	N/A	N/A	No	Yes	Yes	Yes	Yes
3											
4											

DEFECT(S) IDENTIFIED				REMEDIAL ACTION TAKEN				NOTICE & LABEL ISSUED
1								
2								
3								
4								

Outcome of gas installation pipework visual inspection	PASS	Is the Emergency Control Valve access satisfactory	YES	Outcome of gas tightness test	PASS
Outcome of gas supply pipework visual inspection	PASS	Is the Protective Equipotential bonding satisfactory	YES	NEXT INSPECTION DUE ON OR BEFORE:	06/03/2016

SIGNATURES	Report Issued By: Name:	Chris Walters	Signed:		Date Inspected:	06/03/2015	Gas ID No:	3303380
	Report Received By: Name:		Signed:		Date Received:			